

Problem	Possible Causes	Possible Solutions
Flow Marks	Melt and / or mould too cold	<ol style="list-style-type: none"> <li data-bbox="945 139 1545 171">1. Increase barrel and nozzle temperatures. <li data-bbox="945 211 1545 242">2. Increase melt and/or mould temperature. <li data-bbox="945 282 1320 314">3. Increase injection rate. <li data-bbox="945 354 1545 385">4. Increase screw speed and back pressure. <li data-bbox="945 425 1343 457">5. Check suitability of screw.
	Mould design	<ol style="list-style-type: none"> <li data-bbox="945 489 1298 520">1. Change gate location. <li data-bbox="945 560 1208 592">2. Enlarge gates. <li data-bbox="945 632 1224 663">3. Enlarge runners. <li data-bbox="945 703 1477 846">4. Add additional flow-restricting zones (e.g. sprue pullers) to runners.
Short Shots/Filling Problems	Air entrapment due to insufficient venting	<ol style="list-style-type: none"> <li data-bbox="945 854 1410 886">1. Check for obstruction of vents. <li data-bbox="945 925 1291 957">2. Check vent locations. <li data-bbox="945 997 1185 1029">3. Enlarge vents. <li data-bbox="945 1068 1522 1211">4. Change filling behaviour by reducing or increasing injection rate and/or pressure. <li data-bbox="945 1251 1381 1283">5. Add vacuum assist to vents
	Runner system	<ol style="list-style-type: none"> <li data-bbox="945 1283 1381 1314">1. Check for obstruction of gate. <li data-bbox="945 1354 1179 1386">2. Enlarge gate. <li data-bbox="945 1426 1224 1457">3. Enlarge runners.

	Melt and / or mould too cold	1. Increase barrel and nozzle temperatures. 2. Increase mould temperature. 3. Increase injection rate. 4. Increase screw speed.
	Shot weight	1. Increase shot weight. 2. Increase melt cushion.
Sink Marks	Hold pressure too low	1. Increase holding pressure.
	Melt and / or mould too hot	1. Reduce barrel and nozzle temperatures. 2. Reduce mould temperature. 3. Reduce screw speed.
Burn Marks	Melt and / or mould too hot	1. Reduce barrel and nozzle temperatures. 2. Reduce mould temperature. 3. Reduce screw speed.
	Heater(s) stuck on	1. Check thermocouples and heater bands.
	Mould design	1. Enlarge vents. 2. Check for obstruction of vents. 3. Add vacuum assist to vents. 4. Check vent locations.
	Odour or yellowing	1. Reduce barrel and nozzle temperatures. 2. Reduce mould temperature. 3. Reduce injection rate.

		<p>4. Reduce screw speed and back pressure.</p> <p>5. Check temperature of hot runners (if used).</p>
Flashing	Injection pressure / rate too high	<p>1. Reduce injection pressure / rate.</p> <p>2. Increase clamp pressure.</p> <p>3. Reduce injection rate.</p>
	Melt and / or mould too hot	<p>1. Reduce barrel and nozzle temperatures.</p> <p>2. Reduce mould temperature.</p> <p>3. Reduce screw speed.</p>

Problem	Possible Causes	Possible Solutions
Part distortion/ Warpage	Too much orientation	<p>1. Increase melt and mould temperature.</p> <p>2. Reduce injection rate.</p>
	Part is over-packed	<p>1. Reduce holding pressure.</p> <p>2. Match injection time to mould fill time.</p>
	Uneven mould fill	<p>1. Change gate locations.</p> <p>2. Ensure uniform mould temperature.</p> <p>3. Increase injection rate and pressure.</p>
Black specks or undispersed particles	Contamination	<p>1. Purge with low-MFI PP or HDPE.</p> <p>2. Check that colour concentrate is based on PP or PE, not PVC.</p>

Sticking in mould	Part is too hot	1. Reduce barrel and nozzle temperatures. 2. Reduce mould temperature. 3. Increase cooling time.
	Part is over-packed	1. Reduce shot weight and find correct fill point.
	Mould design	1. Increase draft angles. 2. Use non-stick surface treatment. 3. If necessary, erode mould.
Lump formation at gate	Moisture	1. Dry pellets. 2. If using vented screw, check for obstruction of vent. 3. Add vacuum assist to vents.
Voids	Melt freezes too quickly	1. Increase mould temperature. 2. Increase screw speed and pressure.
	Moisture	1. Dry pellets. 2. If using vented screw, check for obstruction of vent. 3. Add vacuum assist to vents.
	Holding pressure too low	1. Increase holding pressure.
	Insert moulding: Inserted part is too cold	1. Preheat part (caution: heat surface only to approx. 80° C – 100° C.)